Independence Fire Department 950 North Spring St. Independence, MO 64050 816-325-7121

Thursday, 2 September, 2021

816-325-7136



Property Address: Shawn Foster ** Short Term Rental ** 3215 S Vermont Ave Independence, MO 64052

Re: Initial - Short Term Rental on September 02 2021

Congratulations, your business has satisfactorily completed and passed the Initial Short Term Rental Fire and Life Safety Inspection. The Independence Missouri Fire Department would like to take this time to thank you for making fire safety a priority.

Upon satisfactory completion and signing off of all inspections by all required City Departments, your City of Independence, Missouri Business License will be sent to the business owner to be displayed within the occupancy.

Note: Records of inspection reports are maintained by the Fire Prevention Bureau of the City of Independence, Missouri Fire Department and are part of the public record requirements of the State of Missouri. It is possible that information contained in these reports in addition to your failure to correct any noted fire code violations may be used against you in civil and/or criminal proceedings in the event of an incident related to any such violation. These records may also be accessed by your insurance carrier.

Inspector:	Property Representative:
Ghradnials	39
Fire Inspector Glenda Knisely	Shawn Foster
gknisely@indepmo.org	

Inspection on September 02 2021 Violations repaired / total: 0 / 0

Violation/Information Page(s)

General Inspection Information

Are address numbers plainly visible and legible from the street and in contrast with the background? Pass
Is the way to the exit obvious and unobstructed? Pass
Is there a map identifying escape routes posted in each guest room? Pass
Is emergency contact information for the owner or manager posted in each guest room? Pass
Is a new or properly tagged, minimum 2A10BC portable fire extinguisher mounted on a bracket in plain view and near an exit? Pass
Are functioning smoke detectors present in each bedroom and common area? Pass
Are child proofed electrical outlets or electrical outlet protectors installed in any unused outlet? Pass
Is a functioning carbon monoxide detector present? Pass
Are heating and refrigeration units maintained with proper 36" clearance from combustibles? Pass
Is the hot water heater equipped with a relief valve and a drain line that extends between 6 to 24 from the floor? Pass
Are breaker/fuse boxes accessible and maintained with 30 inches in width, 36 inches depth and 78 inches in height of clear space in front of the panel with breakers free to operate? Pass