

Independence Fire Department
950 North Spring St.
Independence, MO 64050
816-325-7121



Tuesday, 28 December, 2021

Attn: Gwen Walters
Dale's Dog Boutique ***Home Business***
16804 E Salisbury Rd
64050, MO 64056

Property Address:
Dale's Dog Boutique ***Home Business***
16804 E Salisbury Rd
64050, MO 64056

Re: Initial - Home Based Business on December 28 2021

Congratulations, your business has satisfactorily completed and passed the Initial Home Business License Fire and Life Safety Inspection. The Independence Missouri Fire Department would like to take this time to thank you for making fire safety a priority.

Upon satisfactory completion and signing off of all inspections by all required City Departments, your City of Independence, Missouri Business License will be sent to the business owner to be displayed within the occupancy.

Note: Records of inspection reports are maintained by the Fire Prevention Bureau of the City of Independence, Missouri Fire Department and are part of the public record requirements of the State of Missouri. It is possible that information contained in these reports in addition to your failure to correct any noted fire code violations may be used against you in civil and/or criminal proceedings in the event of an incident related to any such violation. These records may also be accessed by your insurance carrier.

Inspector:

Fire Inspector Robert Frazier

rfrazier@indepmo.org
816-325-7134

Property Representative:

Gwen Walters

Violation/Information Page(s)

General Inspection Information

Are address numbers plainly visible and legible from the street and in contrast with the background?

Pass

Is the way to the exit obvious and unobstructed?

Pass

Are exiting components such as doors, handrails, exit illumination, etc. in proper working order?

Pass

Is trash removed from the premises daily or kept in an approved trash container with a cover?

Pass

Are fuel supply shut-off valves installed within six (6) feet of each gas appliance?

Pass

Are heating and refrigeration units maintained with proper clearance (36) from combustibles?

Pass

Is the hot water heater equipped with a relief valve and a drain line that extends between 6 to 24 from the floor?

Pass

Are breaker/fuse boxes accessible and maintained with 30 inches in width, 36 inches depth and 78 inches in height of clear space in front of the panel with breakers free to operate?

Pass

Is a properly tagged, minimum 2A10BC portable fire extinguisher mounted on a bracket in plain view and near an exit?

Pass

Are functioning smoke detectors present?

Pass

Where required for a nail salon, is an exhaust ventilation system installed. The system must provide six (6) air exchanges per hour.

Pass
